DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-017994 Address: 333 Burma Road **Date Inspected:** 06-Nov-2010

City: Oakland, CA 94607

Project Name: SAS Superstructure OSM Arrival Time: 1100 **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Mr. Tian lei **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** Orthotropic Box Girder (OBG)

Summary of Items Observed:

This CALTRANS OSM Quality Assurance Inspector (QA) Surendra Prabhu was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

BAY-2

The following Non Destructive Testing (NDT) Inspection carried out as per the ZPMC submitted Notification No. 07255.

Ultrasonic Testing (UT)

This QA performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated UT report for this date. The members are identified as OBG Longitudinal diaphragm weld Components. Total number of welds UT Tested: 2 No's. The weld designations are review as follows:

1. LD3049-001-018,022.

This QA Inspector Randomly observed the following work in progress:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Submerged Arc Welding (SAW) of weld joint SA3444-001-001. Welder is identified as 045265. ZPMC Quality Control (QC) is identified as Mr. Zhulin. The welding variables appeared to comply with the Applicable WPS: WPS-B- T-2221-B-L2c-S-2. Refer the attached photos for reference.

SAW of weld joint SA3451-001-001. Welder is identified as 250050. ZPMC Quality Control (QC) is identified as Mr. Zhulin. The welding variables appeared to comply with the Applicable WPS: WPS-B- T-2221-B-L2c-S-2. Refer the attached photos for reference.

BAY-3

The following Non Destructive Testing (NDT) Inspection carried out as per the ZPMC submitted Notification No. 07257.

Ultrasonic Testing (UT)

This QA performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated UT report for this date. The members are identified as OBG Longitudinal diaphragm weld Components. Total number of welds UT Tested: 1 No. The weld designations are review as follows:

1. LD3041-001-022.

Flux Cored Arc Welding (FCAW) of weld joint FB3286-001-202. Welder is identified as 066439. ZPMC Quality Control (QC) is identified as Mr. Zhan hai feng. The welding variables appeared to comply with the Applicable WPS: WPS-B- T-2233-TC-U4c-F.

FCAW of weld joint FB3286-001-232. Welder is identified as 066041. ZPMC Quality Control (QC) is identified as Mr. Zhan hai feng. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-2233-TC-U4c-F.

FCAW of weld joint FB3286-001-274. Welder is identified as 037705. ZPMC Quality Control (QC) is identified as Mr. Zhan hai feng. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-2233-TC-U4b-F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)





Summary of Conversations:

Only general conversation was held between QA and Quality Control (QC) concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Prabhu,Surendra	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer